

Mounting Holes and Mechanical Drawing

The mounting hole that is in the upper right corner (next to the 5V power input) is grounded to the shield of the Ethernet jack. The other 3 mounting holes are not connected to anything. If you use a shielded Ethernet cable, the shield will be connected to the chassis if you use a metal standoff that connects to the chassis. It's hard to say whether that is good or bad since it may or may not be connected to Earth ground on the PC side. It is best to ground a shielded cable at one end only. Here is a drawing showing the board dimensions, mounting hole locations, and the locations of the connectors.

